

**Title: Receiver Bug 001 in AS8202NF**

---

**Subject: Non-Critical Hardware Bug****Description:**

TTP requires a maximum level of error detection on the physical layer as well as on the semantic layer for a received message. Among others the AS8202NF has a built-in ability to detect frames that are shorter or longer than expected. This feature does not correctly work for all situations with MFM and Manchester encoding.

**Effects:**

Frames that are too short or too long can appear to have the correct size.

**Further actions:**

Remove bug in next version.

