
Title: Comments on Dead/Deactivated Code in TASM Software V2.04 of the AS8202NF

Subject:**Position of TTChip related to Dead and Deactivated Code in TASM Software V2.04 of the AS8202NF****Description:**

1. The TASM Software V2.04, which is loaded into the AS8202NF's protocol instruction RAM by the host at power-up, is certified software and does not contain any dead or deactivated code.
2. An application that deactivates some of the features of the TASM Software V2.04 using the MEDL (for example, makes no use of Remote Pin Voting, RPV), will in fact make the TASM Software in protocol instruction RAM contain deactivated code as part of this application.
3. It is the responsibility of the application designer to assure that the selected configuration of the AS8202NF is valid and fits the application requirements. This includes the use of TASM Software V2.04 as the protocol software in the AS8202NF and the use of a proper and consistent MEDL. Granted the selected configuration is valid and fits the application requirements, the resulting deactivated code does not cause any unpredicted behavior of the active code.